· · · · · · · · · · · · · · · · · · ·			EPORT for Tra	acking #674054		
Owner: Bob Quigley			Owner Well #	: 1		
	CR 403		Grid #:	57-10-8		
	see coordinates Llano, TX 78643		Latitude:	30° 46' 08.11" N		
	CR 403		Longitude:	098° 49' 05.38" W		
	see coordinates Llano, TX 78643		Elevation:	1164 ft. above sea leve		
Well County:	Llano					
Number of Wells	Drilled: 9					
Type of Work:	New Well		Proposed Use	e: Stock		
Drilling Method:	6.75 Air Hammer		10	200		
			10	200		
Borehole Comple						
	_		(1)			
Annular Seal Data	Top Depth (ft.)	Bottom Depth		ription (number of sacks & material) Cement 3 Bags/Sacks		
Seal Metho				perty Line (ft.): 50+		
Sealed E	By: Driller		Distance to Septic			
			Distance to Se	eptic Tank (ft.): 150+		
			Method	of Verification: owner		
Surface Completi	on: Surface Sleeve	Installed	Sur	Surface Completion by Driller		
Surface Completion				romant Mathady Steal Tan		
Water Level:	36 ft. below lar	nd surface on 202	4-06-27 Measu	rement Method: Steel Tape		
	36 ft. below lar No Data	nd surface on 202	4-06-27 Measu	rement Method: Steel Tape		
Water Level:		nd surface on 202	4 -06-27 Measu	rement Method: Steel Tape		

	Strata Depth (ft.)	Water Type				
Water Quality:	20	No Data				
	50	No Data				
	Chemical Analysis Made:		Νο			
	Did the driller kno	owingly penetrate any strata which contained injurious constituents?:	No			
Certification Data:	driller's direct supervisio correct. The driller under	the driller drilled this well (or the wel on) and that each and all of the state erstood that failure to complete the r ned for completion and resubmittal.	ments he	rein are true and		
Certification Data: Company Information:	driller's direct supervisio correct. The driller under the report(s) being return	on) and that each and all of the state erstood that failure to complete the r	ments he	rein are true and		
	driller's direct supervisio correct. The driller under the report(s) being return	on) and that each and all of the state erstood that failure to complete the r	ments he	rein are true and		
Company Information:	driller's direct supervisio correct. The driller under the report(s) being return Walden Drilling Inc PO Box 878	on) and that each and all of the state erstood that failure to complete the r	ments he equired it	rein are true and		
	driller's direct supervisio correct. The driller under the report(s) being return Walden Drilling Inc PO Box 878 Llano, TX 78643	on) and that each and all of the state erstood that failure to complete the r ned for completion and resubmittal.	ments he equired it	rein are true and ems will result in		

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description	Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
0	1	topsoil	6	Blank	New Plastic	40	-2	10
1	10	red granite	0	DIAITK	(PVC)	40	-2	10
10	200	black and red granite						

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540