

## STATE OF TEXAS WELL REPORT for Tracking #575563

Owner: <b>Clayton Leverette</b>	Owner Well #: <b>8</b>
Address: <b>110 E. Burnet st Llano, TX 78643</b>	Grid #: <b>57-09-1</b>
Well Location: <b>Hickory Grove see coordinates Pontotoc, TX 76869</b>	Latitude: <b>30° 50' 57.51" N</b>
	Longitude: <b>098° 58' 17.68" W</b>
Well County: <b>Mason</b>	Elevation: <b>1413 ft. above sea level</b>
Number of Wells Drilled: <b>8</b>	

Type of Work: <b>New Well</b>	Proposed Use: <b>Stock</b>
-------------------------------	----------------------------

Drilling Start Date: **6/5/2021**      Drilling End Date: **6/5/2021**

	<i>Diameter (in.)</i>	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>
Borehole:	<b>9</b>	<b>0</b>	<b>10</b>
	<b>6.75</b>	<b>10</b>	<b>260</b>

Drilling Method: **Air Hammer**

Borehole Completion: **Straight Wall**

	<i>Top Depth (ft.)</i>	<i>Bottom Depth (ft.)</i>	<i>Description (number of sacks &amp; material)</i>
Annular Seal Data:	<b>-1</b>	<b>10</b>	<b>Cement 3 Bags/Sacks</b>

Seal Method: **Poured**

Sealed By: **Driller**

Distance to Property Line (ft.): **150+**

Distance to Septic Field or other concentrated contamination (ft.): **200+**

Distance to Septic Tank (ft.): **200+**

Method of Verification: **owner**

Surface Completion: **Surface Sleeve Installed**      **Surface Completion by Driller**

Water Level: **80 ft. below land surface on 2021-06-06**      Measurement Method: **Steel Tape**

Packers: **No Data**

Type of Pump: **No Data**

Well Tests: **Estimated**      **Yield: 5-7 GPM with 0 ft. drawdown after .5 hours**

Water Quality:

<i>Strata Depth (ft.)</i>	<i>Water Type</i>
<b>80</b>	<b>No Data</b>
<b>170</b>	<b>TDS 295</b>

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Walden Drilling Inc**  
**PO Box 878**  
**Llano, TX 78643**

Driller Name: **Brian Walden**

License Number: **59369**

Apprentice Name: **Dustin Wilson**

Comments: **No Data**

Lithology:  
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:  
BLANK PIPE & WELL SCREEN DATA

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
<b>0</b>	<b>10</b>	<b>red granite sand and gravel</b>
<b>10</b>	<b>260</b>	<b>black and red granite</b>

<i>Dia (in.)</i>	<i>Type</i>	<i>Material</i>	<i>Sch./Gage</i>	<i>Top (ft.)</i>	<i>Bottom (ft.)</i>
<b>6</b>	<b>Blank</b>	<b>New Plastic (PVC)</b>	<b>40</b>	<b>-2</b>	<b>10</b>

#### IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation**  
**P.O. Box 12157**  
**Austin, TX 78711**  
**(512) 334-5540**