	STAT	E OF TEXAS	S WELI		RT for Tra	cking #674061		
Owner:	ner: Bob Quigley				Owner Well #:	7		
Address:	CR 403	ee coordinates Iano, TX 78643			Grid #:	57-10-8 30° 46' 20.5" N 098° 49' 09.7" W		
					Latitude:			
Well Location:	CR 403				Longitude:			
					Elevation:	1200 ft. above sea leve		
Well County:	Llano							
Number of Well	ls Drilled:	9						
Type of Work:	New We	ell			Proposed Use: Stock			
Drilling Method: Borehole Comple		6.75 Air Hammer Straight Wall		10		260		
		Top Depth (ft.)	Bottom	Depth (ft.)	t.) Description (number of sacks & m			
Annular Seal Da	ata:	-1		10	C	ement 3 Bags/Sacks		
Seal Meth	nod: Pou	red		D	istance to Prope	erty Line (ft.): 50+		
Sealed	By: Drill	er			ance to Septic F centrated contai	ield or other mination (ft.): 150+		
					Distance to Sep	otic Tank (ft.): 150+		
					Method o	f Verification: owner		
Surface Complet	tion:	Surface Sleeve Installed			Surface Completion by Driller			
Water Level:		34 ft. below land	surface o	n 2024-07 -	•12 Measure	ement Method: Steel Tape		
Packers:		No Data						
Type of Pump:		No Data						
Well Tests:		Estimated	Yield	: 15 GPM	with 0 ft. draw	down after .5 hours		

	Strata Depth (ft.)	Water Type		
Water Quality:	40	No Data		
	220	No Data		
	230	No Data		
		No No		
	Did the driller know c			
Certification Data:	driller's direct supervision) correct. The driller unders	e driller drilled this well (or the well and that each and all of the stater stood that failure to complete the re d for completion and resubmittal.	ments herein are true and	
	driller's direct supervision) correct. The driller unders the report(s) being returne	and that each and all of the stater stood that failure to complete the re	ments herein are true and	
	driller's direct supervision) correct. The driller unders the report(s) being returne	and that each and all of the stater stood that failure to complete the re	ments herein are true and	
Company Information	 driller's direct supervision) correct. The driller unders the report(s) being returne Walden Drilling Inc PO Box 878 	and that each and all of the stater stood that failure to complete the re	ments herein are true and equired items will result in	
Certification Data: Company Information Driller Name: Apprentice Name:	 driller's direct supervision) correct. The driller unders the report(s) being returne Walden Drilling Inc PO Box 878 Liano, TX 78643 	and that each and all of the stater stood that failure to complete the re ad for completion and resubmittal.	ments herein are true and equired items will result in	

Lithology: DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing: BLANK PIPE & WELL SCREEN DATA

Top (ft.)	Bottom (ft.)	Description	Dla (in.)	Туре	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
0	1	topsoil	6	Blank	New Plastic	40	_2	10
1	260	black and red granite	0	DIAIIK	(PVC)	40	-2	10

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation P.O. Box 12157 Austin, TX 78711 (512) 334-5540